Work Orde April-24-14 7:32	r ID 116747 2:13 AM		*116	747*						Page 1	
Revision ID: Item Name: Start Date: Date: Start Date: Date: Start Date:	D3566-13 Gasket Fwd 5/05/14 Start Qty: 12.00 Req'd Qty: 12.00	*12*	Accept	*N900 Cust Item I Customer:		100)* ·	Setup Sta	rt *N ^p *N	S1* S2*	
	Process Plan: _MLS	' '	Tooling: SPC (Y/N):		nte:	-	F	Run Sta	D ~!/J	R1* R2*	
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
Draw Nbr	Revision Nbr	· · · · · · · · · · · · · · · · · · ·								<u> </u>	
D3566	Rev C										
*100 *100* Waterjet FLOW CNC Waterjet	FLOW WATER JET Memo 1-Cut as p Deburr if	er Dwg D3566 Dwg Rev: necessary	0.00 O.00 Prog Rev:	<u>~</u> 2-				D		Jm14-05-11	
*110 *110* QC Quality Control	· QC2- Inspect parts off Memo	machine FAI/FAIB	0.00					٥		JM14-05-	Ц
120 *1 20* QC	QC8- Inspect parts - se	econd check	0.00 27 9-89 0.00 WIS	9			<u>り</u>				
4 0	Memo		0.00 1								

Quality Control

DQA:			Date:											
						WORK ORDER NON	-CC	NFO	RMANCE / UPDATE					AEROSPACE
QA Closed:			Date:							Wo	ork Order up	date only		
Mork Ordo						DISPOSITION			AGAINST	DE	PARTMENT	/PROCESS		
Work Orde					—	Rework	1 i		Skid-tube Crosstube			Water Jet		Engineering
Part N	lo					Scrap	1		Machining Small Fab		Pro	d. Eng. Coor.		Quality
, until	•					Use-as-is	1		noforming Finishing			re/Packaging		Other
NCR N	lo.					Suspected Unapproved			Large Fab Composite		•	Supplier		
	•						1		· · · · · · · · · · · · · · · · · · ·					
Root					Desc	ription of work order update	1	nitial	Action		Sign &			
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Description		Date	Verificatio	n	QC Inspector
Design	_	•												
Doc/Data														
Equip/Tooling	_						1							
Handling/Pre														
Material									i					
Operator	ᅴ													
Offset/Setup	_													
Process														
Supplier	-													
Training			 											
Transport Unapproved														
Onapproved			1	<u> </u>	1	H415-1	FΔI	ULT CA	TEGORY	_	l	1,		
Landir	ng G	iear				General								****
	,,	Bending				Bend	Г	Folio/F	Program	Γ	Outside Dim	ensions		Pressure/Forced
		Centre No	ot Concer	ntric		BOM/Route		Grain	ŭ		Over/Under	tolerance		Set-up
		Cracks			<u> </u>	Broken/Damage/Defect		Hardwa	are	Г	Part Incorre	ci		Temperature/Cure
		Crimp/Kir	nk/Ripple	/Wave		Burrs		Inspect	tion Incomplete/Unqualified		Part Lost/M	issing		Weld
		Cuffs				Contamination		Instruc	tions Incomplete/Unclear		Part Moved			Wrong Stock Pulled
		Crushing				Countersink		Misali	gned/off center		Positioned \	Vrong		-
		Heat Trea	at			Cut Too Short		Mislab	eled		Power Loss,	/Surge		Other
		Inspectio	n Strip in	Tube		Drawing		Misrea	d			***		
		Marks/Ch	natter			Drill Holes		Off-set					_	
	<u> </u>	Turning S	-			Finish		Out of	Calibration					
1	1	Wave/Tw	vist in Tul	эe		Fit/Function		Out of	Sequence					

DQA:			Date:			WORK ORDER NON-	cc	NICOI	DNANICE / LIDDAT	rc			DART
QA Closed:			Date:			WORK ORDER NON-	-((JINFOI	RIVIAINCE / OPDAT		ork Order up	date only	AEROSPACE
Mork Orde						DISPOSITION			AG	GAINST DE	PARTMENT/	PROCESS	
Work Orde	: i .				_	Rework	1		Skid-tube Cro	sstube		Water Jet	Engineering
Part N	lo.					Scrap		1	\vdash	nall Fab	Prod	d. Eng. Coor.	Quality
	•					Use-as-is			У —	nishing		e/Packaging	Other
NCR I	NCR No.				Suspected Unapproved		Large Fab Composite				Supplier		
Root					Desci	ription of work order update		nitial	Action		Sign &		
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Description)	Date	Verification	QC Inspector
Design													
Doc/Data													
Equip/Tooling													
Handling/Pre	Ш							J					
Material													
Operator					ļ								
Offset/Setup					Ì								
Process	Ш										,		
Supplier													
Training													
Transport				İ									
Unapproved					<u> </u>		<u> </u>		İ				
							FA	ULT CA	TEGORY			_	
Landi	ng (I				General	_	1			1	. –	¬_
		Bending				Bend	<u> </u>	-	Program		Outside Dim	_	Pressure/Forced
		Centre No	ot Concer	ntric	_	BOM/Route		Grain		·	Over/Under	<u> </u>	Set-up
	\vdash	Cracks				Broken/Damage/Defect	<u> </u>	Hardwa			Part Incorred	<u> </u>	Temperature/Cure
	-	Crimp/Kir	ık/Ripple	:/Wave		Burrs		1	ion Incomplete/Unqualif		Part Lost/Mi		Weld
		Cuffs			<u> </u>	Contamination	_	4	tions Incomplete/Unclear	r	Part Moved		Wrong Stock Pulled
		Crushing			<u> </u>	Countersink	<u></u>	•	gned/off center	<u> </u>	Positioned V	_	٦
	<u> </u>	Heat Trea			<u> </u>	Cut Too Short	\vdash	Mislab			Power Loss/	Surge	Other
	<u> </u>	Inspectio		Tube	\perp	Drawing	\vdash	Misrea					
	_	Marks/Ch				Drill Holes	\vdash	Off-set					
	<u></u>	Turning S	•			Finish	_	-1	Calibration		<u></u>		
	1	Wave/Tw	ist in Tul	эe		Fit/Function		Out of	Sequence				

April-24-14 7:32:16 AM

Work Order ID: 116747

116747

Parent Item:

D3566-13

D3566-13

Parent Item Name: Gasket Fwd

Start Date: 5/05/14

Required Date: 5/05/14

Start Qty: 12.00

Required Qty: 12.00

Comments:

New Issue 07-03-08 ec IPP Rev:A

IPP Rev:B Added Drain Holes 07-07-09 JLM

IPP Rev:C As per Rev C 07-09-09 JLM Verified By;EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch		Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MNEO60S.063		Purchased	No			100	sf	896.8000	0.195 (3			
MNFO60	S 063								**			Ton	14-05-

NEOPRENE SHEET 0.063

Location	Loc Qty	Loc Code	
MAT052	896.8		
M126546	27.1	•	
M128266	69.7		
M128339	800		128339

Page 1

DQA:	Date:								_				TRACT	_
0.4.61			D-4			WORK ORDER NON-	-CC	ONFO	RMANCE / UF		Nort Ordon	ndoto only	AEROSPACE	
QA Closed:			Date:				-				Vork Order u	poate only		7
Work Orde	er:					DISPOSITION				AGAINST D	EPARTMEN	/PROCESS		
	-			<u></u>		Rework	ı		Skid-tube	Crosstube	7	Water Jet	Engineering	
Part N	۱o.					Scrap			Machining	Small Fab	Pro	od. Eng. Coor.	Quality	
	-					Use-as-is			noforming	Finishing		re/Packaging	Other	
NCR N	No					Suspected Unapproved			Large Fab	Composite		Supplier		Ì
											- T	·		4
Root					Desci	ription of work order update		nitial	Acti		Sign &			
Cause	,	Date	Step	Qty		or non-conformance	Ch	ief Eng	Descr	iption	Date	Verification	n QC Inspector	\dashv
Design														1
Doc/Data	\square					!								١
Equip/Tooling														
Handling/Pre														
Material	Щ													9
Operator			ļ											
Offset/Setup	Ш		·				ļ							
Process	Ш													
Supplier				İ										
Training														
Transport	Ш								ļ					
Unapproved										·		<u> </u>		╝
							FA	ULT CA	TEGORY					╛
Landi	ng G	Sear			_	General		-		_		F		
	Ш	Bending				Bend		Folio/F	Program		Outside Dii	nensions	Pressure/Forced	
		Centre No	ot Concer	ntric		BOM/Route		Grain			Over/Unde	r tolerance	Set-up	
		Cracks				Broken/Damage/Defect		Hardwa	are		Part Incorr	eci	Temperature/Cure	
		Crimp/Kii	nk/Ripple	/Wave		Burrs		Inspect	tion Incomplete/Ur	nqualified	Part Lost/N	lissing	Weld	
		Cuffs				Contamination		Instruc	tions Incomplete/L	Jnclear	Part Move	ı [Wrong Stock Pulled	
•		Crushing				Countersink		Misali	gned/off center		Positioned	Wrong	_	
		Heat Trea	at			Cut Too Short		Mislab	eled		Power Loss	/Surge	Other	
		Inspectio	n Strip in	Tube		Drawing		Misrea	d ·					
		Marks/Cl	natter			Drill Holes		Off-set						
		Turning S	equence			Finish		Out of	Calibration					
		Wave/Tw	ist in Tul	эe		Fit/Function		Out of	Sequence					

DART AEROSPACE LTD	Work Order: 116747	
Description: Gasket	Part Number: D3566-13	
Inspection Dwg: D3566 Rev: C	Page 1 of 1	

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

				7 1		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
7.00	+/-0.030	700	_		ν	JEMOS
3.50	+/-0.030	3.50`	_		V	
2.43	+/-0.030	2.43"	_		V	
3.10	+/-0.030	3.10"	-		V	
0.30	+/-0.030	0.30	^		V .	
0.30	+/-0.030	0.300			V	
0.063	+/-0.010	0.063	_		ν	
Ø0:188	+0.005/-0.001	0.190			V	
						_
				Ī		

Measured by: $\int \mathcal{M}$ Audited by: $\frac{27}{9-89}$ Prototype Approval: N/A

Date: $|\mathcal{U}| = 0.5 - 1.1$ Date: $|\mathcal{V}| = 0.5 - 1.1$ Date: N/A

Rev	Date	Change	Revised by	Approved
Α	07.04.20	New Issue	KJ/JLM	
В	07.07.18	Dimensions updated per Dwg Rev. B	KJ/JLM ,	
С	08.09.04	Dwg Rev updated	KJ/DD 🚜	<i>M</i>

